



## Wolfjaw™

Full Brim Smooth Dome Hard Hat with Fiberglass Resin Shell, 8-Point Riveted Textile Suspension and Wheel-Ratchet Adjustment

- Fiberglass resin shell withstands radiant temperatures up to 350° F
- Smooth dome shape with exposed rivets is popular in Construction, Industry and Metalworking
- 8-Point riveted textile suspension for increased comfort and force displacement
- Durable wheel adjustment system for one hand size adjustments
- Soft, non-chaffing, EVA moisture management sweatband padding for maximum sweat absorption
- Three position height adjustment settings to ensure proper depth

## Applications

- Mining
- Tunneling
- Demolition
- Utility Work
- Metalworking

## Technical Data

|                      |                                     |
|----------------------|-------------------------------------|
| Color                | Black, White, Yellow, Natural Brown |
| Sizes Available      | OS                                  |
| Packaging            | Boxed                               |
| Packed               | 12/Case                             |
| Case Dimensions (cm) | 61.00 x 36.00 x 58.00               |
| Case Weight (kg)     | 8.90                                |
| Country of Origin    | China                               |
| Shell Material       | Fiberglass Composite                |
| Shell                | Non-Vented                          |
| Brim Style           | Full                                |
| Brim Length          | Standard                            |
| Size Adjustment      | Wheel Ratchet                       |
| Suspension           | Polyester Textile Straps            |
| Chin Strap           | --                                  |
| Sweatband            | Felt Lined Foam                     |
| Size Range           | 53cm-63cm                           |
| Construction         | --                                  |
| Certifications       | ANSI/ISEA Z89.1                     |
| Product Circularity  | --                                  |

## Performance Data

|                  |         |
|------------------|---------|
| ANSI Type        | Type I  |
| CSA Type         | --      |
| Electrical Class | Class G |

## Care Instructions

The unit may be cleaned with soap and warm water and dried with a soft cloth. The helmet should not be cleaned with chemical or abrasive cleaners. The helmet should be stored out of direct sunlight, away from chemicals and not exposed to extremes of temperature.