


SPECIFICATION SHEET STYLE: HP341RCAN







Performance Data

ANSI Type	Type I
CSA Type	Type 1
Electrical Class	Class E

Care Instructions

The unit may be cleaned with soap and warm water and dried with a soft cloth. The helmet should not be cleaned with chemical or abrasive cleaners. The helmet should be stored out of direct sunlight, away from chemicals and not exposed to extremes of temperature.



Dom™

Cap Style Hard Hat with HDPE Shell, 4-Point Nylon Suspension and "Sure-Lock" Ratchet Adjustment - Type 1 Class E

- Smooth dome shape is ideal for welding applications & attachments
- Shell Has Rain Trough For Extra Convenience
- Large Printing Surfaces For Great Custom Logo's on Front, Sides & Back
- Exclusive "SURE-LOCK" Ratchet Adjustment Suspension
- Accessory Slots & Chin Strap Attachments
- CSA Z94.1-15 Certified Type 1 Class E